


HEADQUARTERS
PHILIPPINE ARMY
OFFICE OF THE ARMY QUARTERMASTER
Fort Andres Bonifacio, Metro Manila

HYDRATION PACK, OLIVE DRAB (OD) – 3 L CAPACITY

QM SPEC NR IE-22HPOD dtd 28 July 2015 with
Amendment 1 dated 8 September 2018

VISUAL INSPECTION CHECKLIST

DESCRIPTION OF DEFECTS	CLASSIFICATION OF DEFECTS
1. Packing and Packaging	
a. Contents of carton label not as specified	Minor
b. Each Hydration Pack shall be in a transparent cellophane bag.	Minor
c. Twenty (20) pieces of Hydration Pack shall be packed in a corrugated carton.	Major
d. The top cover when closed shall be sealed with a binding tape and secured with nylon straps.	Minor
2. Not PHILARPAT in color and design	Major
3. Any component part missing:	
a. Sip Tube with cover	Major
b. Bite Valve	
c. Cleaning Paraphernalia	Major
d. Snap Fastener	Major
e. D-ring	Major
f. Grommet	
g. Quick Release Buckles	Major
h. Adjustable Buckles	Major
i. Padding	Major
j. Straps	Major
4. Loose sewing/Untrimmed thread ends	Minor
5. ARMY marking:	
a. Provided with ARMY marking	Major
b. Printed on the center of the flap cover	Minor
c. Printed with black waterproof paint	Major
6. Contractor's label	
a. Printed at the inside back part of the cover	Major
b. Printed with black waterproof paint	Major
c. Contents of the label not as specified	Minor
7. Presence of dirt, stains and other defects:	
a. Affecting appearance	Major
b. Does not affect appearance	Minor


AURELIO T. BADAJOS
Colonel, QMS (GSC)PA
Chief, AQM